





















- Your safety is extremely important
- Heavy loads and large equipment can present special risks
- Do not place yourself in harm's way
- Make eye contact with heavy equipment operators
- Wear PPE and safety vests
- Be extremely cautious about entering the area between the pipe and ditch, standing next to the ditch and entering the ditch to observe welding







Where are you standing?









- Pipe on skids can move and fall
- Where would you park?











• Do you want to be under these wires or near this equipment?

























Coating Issues

Construction Issues









Coating Damage

Due to Pipe Support













Coating Issues

Jeeping Over Soil

EXPLOSIVE











- Poor application practices
- Soil stress can remove poorly installed patch stick repairs
- Heating the patch stick and dripping the product on the coating holiday is not acceptable
- The photo shows a poorly adhered patch stick repair
 - This was found upon uncovering a newly built pipeline









- Manufacturer's procedures for patch stick application must be followed
- The photo shows an applied patch stick repair scratched off by a fingernail







Good patch stick application

- Notice heated/discolored area around patch
- This indicates the pipe was heated before and during patch stick application









Only for Pinhole or Abrasion Repair

2-Part Epoxy Should Have Been Used























Coating Issues











Damage by Welding or Beveling Band













2-Part Epoxy

- Follow manufacturer's instructions
- Preparation required (Sanding = anchor pattern)
- Thoroughly mix product
- Use promptly
- If products start to cure before application, the repair presents the appearance of the next slide










Coating Issues












Coating Issues











Electronic Holiday Detection (Jeeping)

- Visual inspection must supplement jeeping
- Problems identified
- Bent defective spring
 - Not identifying and repairing all "jeeps"
- Passing over visible holiday without the jeep sounding
 - Based on experience, jeep voltage may need to be set as high as 3500V to detect coating defects







Bent Spring

A bent jeep spring can miss coating holidays









Overstretched Spring















Coating Issues

• 199 jeeps on section











Jeeping Issues

- Are the workmen finding coating holidays?
- Do the workmen operating the jeep have time to find and repair coating holidays?
- Is the jeep turned on?









Jeeping Over Attachments

Manipulating the jeep spring over building fiberboard stuck to the pipe is poor practice







Jeeping at Skids

Jeeping at skids only on lowering in is not usually per construction procedures









Duct Tape

Duct tape can shield coating holidays







Backfill Practices

Damage Due to Poor Backfill Practices











Backfill Practices

- Look for coating holidays in the ditch
- Observing these indicates a problem







Backfill Practices















Backfill Issues

- Rock Padding Rock Shield
- Record area where RS applied









Padding Machine











Backfill Issues











Thin Film Epoxy Issues

- Insufficient heating
 - 3M procedure specify $425^{\circ} 488^{\circ}$ F
 - Lower temperatures could mean improper curing
- Over heating during application can be a problem
 - Coating looks burnt and is unacceptable
- Poor sandblasting









Thin Film Epoxy Issues











Girth Weld Coating











425°F to 488°F












Thin Film Epoxy Issues











No Coating Coverage

Is there water in the pipe?











Gouges and Bending

- Consult procedures
- Acceptable wall thickness?
- < 1% diameter?









Proper Burial Depth on Bores









Deep Enough/Protected from Erosion









Laminations

Can be an issue especially associated with an 80% waiver












Automated Ultrasonics (AUT)

Easily shows laminations






























































Rock Shield Needed






























ADB-10-03 Girth Weld Quality Issues

- Misalignment
- Thickness transitions
- Welding practices
- Below in-service failure occurred at 65% SMYS










ADB-10-03 Girth Weld Quality Issues












Bends and Fittings

- Bend fittings
- Hot induction bends
- If cutting bends, use segmentable bends with tighter body tolerance
- Ends should meet:
 - API 5L dimensional limits
 - API 1104 fit-up requirements



Hot induction bend cross-section







Caliper Pig

















Anomaly Dig



Pipe on Solid Rock










DCVG Dig on First Phase





DCVG Dig












DCVG Dig











DCVG Dig on First Phase

Girth weld coating mixed with backfill



Wet Epoxy Mixed with Backfill







Are There Sufficient Weights?









Protected from Rocks in the Ditch











Pipe Defect

Does remaining wall thickness meet requirements of API 5L?











Grinding Remaining W.T.











Thank you









SAFETY IS IN YOUR HANDS. **EVERY DIG. EVERY TIME.**

